

Date: 20-February-2025

Time: 09:36:32

Title: **A28, Chart Rd, Ashford**

Requested output: **D - Print Crash Report**

Date: 20-February-2025

Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

There were 20 reported crashes resulting in injury

# D-PRINT CRASH REPORT

20-Feb-2025

09:36:32

A28, Chart Rd, Ashford

Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
1	Road No A28 Grid 599147E Section 152 Ref 142521N	SLIGHT	22/08/2023	3	14:00	L	Dry	Fine	S	S.VEH	
	A28 GREAT CHART BYPASS J/W 28 GREAT CHART RNDT, ASHFORD									Ashford	PED
	Taken from OLR; As C1 was waiting for an opportunity to cross, a vehicle stopped and the driver signalled them to cross. C1 crossed and then another car V1 from the other lane, going in the same direction, hit them on their right side. C1 cannot remember what happened immediately afterwards but woke up with a head injury and the right side of their body and back was in pain. The driver stopped and took them to the hospital.						Veh1, car, W -> E			Casualties 1 Vehicles 1	
2	Road No A28 Grid 599198E Section 152 Ref 142484N	SLIGHT	21/10/2022	6	00:32	DRK STU	Dry	Fine		S.VEH	
	A28, GREAT CHART BYPASS RNDT J/W B2229, ASHFORD.									Ashford	
	V1 (unmarked police vehicle) has observed a vehicle travelling in opposite direction with rear light out. V1 has turned around and made after vehicle, approaching roundabout at speed and offside roundabout. V1 has struck roundabout kerb on nearside and then struck offside of V1 on opposite kerb, mounted pavement, and come to a rest in centre of road.						Veh1, car, SW -> NE			Casualties 1 Vehicles 1	

## Key Involved

PED Pedestrian  
HGV Heavy Goods Vehicle  
GV Goods Vehicle  
M/C Motor Cycle  
P/C Pedal Cycle  
PSV Bus/Coach

## Street Lighting

L Daylight  
STL Street Lights  
USL Street Lights Unlit  
NSL No Street Lights  
STU Street Lights Unknown

## FACTORS

+VE Positive Breath Test  
R.TURN Right Turn Manoeuvre  
O/TAKE Overtaking Manoeuvre  
S.VEH Single Vehicle

## Special Conditions

ATS OUT Traffic Lights Not Working  
ATS DEF Traffic Lights Defective  
SIGNS Road Signs Defective or Obscured  
RD WRKS Road Works  
Surface Road Surface Defective

# D-PRINT CRASH REPORT

20-Feb-2025

09:36:32

A28, Chart Rd, Ashford

Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
3	Road No A28 Grid 599199E Section 152 Ref 142517N	SLIGHT	28/11/2021	1	16:32	DRK STL	Dry	Fine			M/C
	A28, GREAT CHART BYPASS J/W CHART RD, ASHFORD.								Ashford		
	V2 has been coming from Chart Rd intending to navigate a rndbt to take the second exit down Brookfield Rd. V1 has been coming from north down Chart Rd A28 (a separate chart rd). V1 was intending to navigate the roundabout to take its second exit to continue down A28. V1 has pulled out into the path of V2 causing a collision.						Veh1, car, NE -> W Veh2, m/cycle 50 - 125cc, W -> SE			Casualties 1 Vehicles 2	
4	Road No A28 Grid 599201E Section 152 Ref 142514N	SLIGHT	12/08/2022	6	17:00	L	Dry	Fine			P/C
	A28, CHART RD RND BT J/W BROOKFIELD RD, ASHFORD.								Ashford		
	OLR: R2 was riding across the road, D1 was Looking right, towards the bridge on Chart Rd. As R2 came off the pavement V1 came shooting out to turn left towards Matalan, at no point did they look left. R2 noticed that D1 wasn't stopping and was too slow on the brake. R2 tried to speed up, V1 hit back wheel and part of the frame and R2 landed on the roundabout.						Veh1, car, NE -> SE Veh2, pedal cycle, E -> W			Casualties 1 Vehicles 2	

## Key Involved

PED Pedestrian  
HGV Heavy Goods Vehicle  
GV Goods Vehicle  
M/C Motor Cycle  
P/C Pedal Cycle  
PSV Bus/Coach

## Street Lighting

L Daylight  
STL Street Lights  
USL Street Lights Unlit  
NSL No Street Lights  
STU Street Lights Unknown

## FACTORS

+VE Positive Breath Test  
R.TURN Right Turn Manoeuvre  
O/TAKE Overtaking Manoeuvre  
S.VEH Single Vehicle

## Special Conditions

ATS OUT Traffic Lights Not Working  
ATS DEF Traffic Lights Defective  
SIGNS Road Signs Defective or Obscured  
RD WRKS Road Works  
Surface Road Surface Defective

# D-PRINT CRASH REPORT

20-Feb-2025

09:36:32

A28, Chart Rd, Ashford

Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved	
5	Road No A28 Section 152	Grid 599218E Ref 142561N	SLIGHT	07/09/2023	5	08:20	L	Dry	Fine		O/TAKE	
	A28, CHART RD, ASHFORD (MAPPED TO COORDS)									Ashford		
	OLR: There was a vehicle in front of V2 and one vehicle to its offside after they exited the rndbt which D2 let pass in front. The road then goes back to single c/way where D2 saw V1 trying to pass on D2's offside but there was no room either in front or behind it for them. D1 was trying to force V2 up the kerb and into metal railings, D1 then pulled across hitting V2 and pulling rear bumper off. D1 was rude and refused details, then shot off going past V2 then swerved back across the road and dislodged V2's front bumper.							Veh1, car, SW -> NE Veh2, car, SW -> NE			Casualties Vehicles	1 2
6	Road No A28 Section	Grid 599261E Ref 142604N	SLIGHT	31/03/2022	5	16:50	L	Dry	Fine			
	A28, CHART RD, ASHFORD (MAPPED TO COORDS)									Ashford		
	OLR: D2 driving west approaching Matalan roundabout on A28, traffic starting to compress and came to a standstill. V2 came to a stop with plenty of room. V1 behind drove straight in the back of V2 while stationary. D1 started throwing hands in the air and shouting at D2.							Veh1, car, NE -> SW Veh2, car, NE -> SW			Casualties Vehicles	2 2

## Key Involved

PED Pedestrian  
 HGV Heavy Goods Vehicle  
 GV Goods Vehicle  
 M/C Motor Cycle  
 P/C Pedal Cycle  
 PSV Bus/Coach

## Street Lighting

L Daylight  
 STL Street Lights  
 USL Street Lights Unlit  
 NSL No Street Lights  
 STU Street Lights Unknown

## FACTORS

+VE Positive Breath Test  
 R.TURN Right Turn Manoeuvre  
 O/TAKE Overtaking Manoeuvre  
 S.VEH Single Vehicle

## Special Conditions

ATS OUT Traffic Lights Not Working  
 ATS DEF Traffic Lights Defective  
 SIGNS Road Signs Defective or Obscured  
 RD WRKS Road Works  
 Surface Road Surface Defective

# D-PRINT CRASH REPORT

20-Feb-2025  
09:36:32

A28, Chart Rd, Ashford  
Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
7	Road No A28 Grid 599378E Section 156 Ref 142762N	SLIGHT	18/01/2024	5	15:56	L	Dry	Fine			M/C
	A28, CHART RD, ASHFORD, (MAPPED TO COORDS).								Ashford		
	Due to it being 'rush hour' there was a lot of stationary traffic on the road. The sun was very low and was dazzling D1's eyesight. D1 has stated they couldn't see the tail lights of R2 in front and could only see the cars down the road ahead due to the sun. V1 wasn't driving any faster than 5mph as V2 has very minimal damage and R2 had stumbled off their bike.						Veh1, car, NE -> SW Veh2, m/cycle 50 - 125cc, NE -> SW			Casualties 1 Vehicles 2	
8	Road No A28 Grid 599439E Section 156 Ref 142854N	SERIOUS	14/06/2024	6	17:23	L	Dry	Fine			P/C
	A28, CHART RD J/W BRUNSWICK RD, ASHFORD.								Ashford		
	V1 was travelling along Chart Rd when R2 has left the pavement and attempted to cross the road. R2 failed to look for oncoming vehs and pulled straight off the pavement into the carriageway. V1, possibly going too fast, has struck R2.						Veh1, car, SW -> NE Veh2, pedal cycle, NE -> SW			Casualties 1 Vehicles 2	
9	Road No A28 Grid 599493E Section 157 Ref 142862N	SLIGHT	19/03/2023	1	10:24	L	Dry	Fine			GV
	A28 BRUNSWICK RD, ASHFORD (MAPPED TO DESC).								Ashford		
	OLR: V2 was coming up Brunswick Rd opposite VJ technology and went to go in the slip road up towards the traffic lights heading towards Matalan. All of a sudden there was a massive clunk and screech, V1 had hit the side of V2. D1 did not stop and headed towards great chart.						Veh1, goods < 3.5t, NE -> SW Veh2, car, NE -> SW			Casualties 2 Vehicles 2	

## Key Involved

PED Pedestrian  
HGV Heavy Goods Vehicle  
GV Goods Vehicle  
M/C Motor Cycle  
P/C Pedal Cycle  
PSV Bus/Coach

## Street Lighting

L Daylight  
STL Street Lights  
USL Street Lights Unlit  
NSL No Street Lights  
STU Street Lights Unknown

## FACTORS

+VE Positive Breath Test  
R.TURN Right Turn Manoeuvre  
O/TAKE Overtaking Manoeuvre  
S.VEH Single Vehicle

## Special Conditions

ATS OUT Traffic Lights Not Working  
ATS DEF Traffic Lights Defective  
SIGNS Road Signs Defective or Obscured  
RD WRKS Road Works  
Surface Road Surface Defective

# D-PRINT CRASH REPORT

20-Feb-2025

09:36:32

A28, Chart Rd, Ashford

Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
10	Road No A28 Section 158 Grid 599576E Ref 142985N	SLIGHT	26/04/2024	6	10:00	L	Dry	Fine			
	A28, CHART RD J/W LOUDON WAY, ASHFORD, (MAPPED TO DESCRIPTION).									Ashford	
	OLR: At the Lotus Drive traffic lights on Chart Rd, V2 was stationary, P1 could see D1 in the car behind on their phone. V1 crashed into the back of V2 as D1 was paying attention to their phone. V2 has a tow bar in the back V1's front grill was damaged. Ages & VRMs not stated.						Veh1, car, NE -> SW Veh2, car, NE -> SW			Casualties Vehicles	2 2
11	Road No A28 Section Grid 599646E Ref 143010N	SLIGHT	15/01/2022	7	11:38	L	Frost/Ice	Fine			
	A28, CHART RD, ASHFORD (MAPPED TO COORDS)									Ashford	
	V1 travelling towards Matalan following V2 in slow moving traffic along Chart Road A28. V2 slowed down for traffic in front, V1 didn't stop in time, hitting V2.						Veh1, car, NE -> SW Veh2, car, NE -> SW			Casualties Vehicles	4 2
12	Road No A28 Section 159 Grid 599667E Ref 143018N	SLIGHT	16/03/2024	7	08:40	L	Wet/Damp	Rain			HGV M/C
	A28, CHART RD, ASHFORD, (MAPPED TO GRID REFS).									Ashford	
	V2 was driving east on Chart Rd in the direction of Ashford. V2 has slowed due to another car turning in the junction ahead. Speed of V2 at the time was around 2mph and slowing to a full stop. D2 heard the revving of R1 coming from behind. R1 has then collided with the back of V2. V2 is a recovery truck carrying a car on the back. R1 has hit the back of veh that was on V2 causing damage to the tailgate panel. R1 has hit the vehicle with helmet.						Veh1, m/cycle > 500cc, SW -> NE Veh2, goods 3.5 - 7.5t, SW -> NE			Casualties Vehicles	1 2

## Key Involved

PED Pedestrian  
HGV Heavy Goods Vehicle  
GV Goods Vehicle  
M/C Motor Cycle  
P/C Pedal Cycle  
PSV Bus/Coach

## Street Lighting

L Daylight  
STL Street Lights  
USL Street Lights Unlit  
NSL No Street Lights  
STU Street Lights Unknown

## FACTORS

+VE Positive Breath Test  
R.TURN Right Turn Manoeuvre  
O/TAKE Overtaking Manoeuvre  
S.VEH Single Vehicle

## Special Conditions

ATS OUT Traffic Lights Not Working  
ATS DEF Traffic Lights Defective  
SIGNS Road Signs Defective or Obscured  
RD WRKS Road Works  
Surface Road Surface Defective

# D-PRINT CRASH REPORT

20-Feb-2025

09:36:32

A28, Chart Rd, Ashford

Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
13	Road No U Section 001	Grid 599750E Ref 142526N	SERIOUS	09/12/2023	7	10:45	L	Wet/Damp	Rain		GV
	LEACON RD J/W IND EST, ASHFORD.									Ashford	
	V1 has been leaving the industrial area to join Leacon Rd at the junction when V2 travelling east has collided with the front of V1.						Veh1, goods < 3.5t, N -> S Veh2, car, NW -> SE			Casualties 4 Vehicles 2	
14	Road No A28 Section 160	Grid 599758E Ref 143043N	SLIGHT	30/05/2024	5	17:20	L	Dry	Fine	R.TURN	
	A28, CHART RD J/W HILTON RD, ASHFORD.									Ashford	
	OLR: V1 pulled out of Hilton Rd onto Chart Rd apparently without looking right, drove into side of V2 as it was driving past along Chart Rd. V1 failed to stop, turned right and drove off despite significant damage. Accident witnessed, name taken, CCTV requested.						Veh1, car, S -> NE Veh2, car, NE -> SW			Casualties 1 Vehicles 2	
15	Road No A28 Section	Grid 599760E Ref 143045N	SLIGHT	24/05/2022	3	16:29	L	Wet/Damp	Rain	R.TURN	
	A28, CHART RD J/W HILTON RD, ASHFORD									Ashford	
	V1 was waiting to contravene a two way junction on Hilton Rd going onto Chart Rd. A vehicle in the first lane in front has waved for D1 to go, however D1 has misjudged and not seen V2 in the second lane and has hit them front on and made contact with their offside drivers door.						Veh1, car, S -> N Veh2, car, W -> S			Casualties 1 Vehicles 2	

## Key Involved

PED Pedestrian  
HGV Heavy Goods Vehicle  
GV Goods Vehicle  
M/C Motor Cycle  
P/C Pedal Cycle  
PSV Bus/Coach

## Street Lighting

L Daylight  
STL Street Lights  
USL Street Lights Unlit  
NSL No Street Lights  
STU Street Lights Unknown

## FACTORS

+VE Positive Breath Test  
R.TURN Right Turn Manoeuvre  
O/TAKE Overtaking Manoeuvre  
S.VEH Single Vehicle

## Special Conditions

ATS OUT Traffic Lights Not Working  
ATS DEF Traffic Lights Defective  
SIGNS Road Signs Defective or Obscured  
RD WRKS Road Works  
Surface Road Surface Defective

# D-PRINT CRASH REPORT

20-Feb-2025

09:36:32

A28, Chart Rd, Ashford

Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
16	Road No U Section 001	Grid 599767E Ref 143012N	SLIGHT	26/06/2024	4	12:30	L	Dry	Fine		GV
	HILTON RD J/W BRUNSWICK RD, ASHFORD.									Ashford	
	OLR: V1/van drove in to the back of V2 after D2 letting a vehicle out of the junction. V2 had began to pull away as V1 hit the rear. D1 had previously been driving very fast in and around cars prior to this.							Veh1, goods < 3.5t, N -> SE Veh2, car, N -> SW		Casualties 1 Vehicles 2	
17	Road No A28 Section 496	Grid 599958E Ref 143142N	SLIGHT	17/08/2023	5	17:05	L	Dry	Fine		P/C
	A28 SIR HENRY BRACKENBURY RD J/W IMPERIUM, ASHFORD (RE-MAPPED TO DESC).									Ashford	
	OLR: R2 came off the rndbt, heading home towards Screwfix when V1 pulled out of the junction from the Imperium facilities in front of R2, V1 pulled out part way leaving a gap in front, they had nowhere to go as they were trying to cross the road to join the traffic going in the other direction. As there was a gap R2 passed in front of V1 and then they drove into R2. R2 hit the bonnet on the right side and then fell into the road.							Veh1, car, S -> N Veh2, pedal cycle, E -> W		Casualties 1 Vehicles 2	

## Key Involved

PED Pedestrian  
HGV Heavy Goods Vehicle  
GV Goods Vehicle  
M/C Motor Cycle  
P/C Pedal Cycle  
PSV Bus/Coach

## Street Lighting

L Daylight  
STL Street Lights  
USL Street Lights Unlit  
NSL No Street Lights  
STU Street Lights Unknown

## FACTORS

+VE Positive Breath Test  
R.TURN Right Turn Manoeuvre  
O/TAKE Overtaking Manoeuvre  
S.VEH Single Vehicle

## Special Conditions

ATS OUT Traffic Lights Not Working  
ATS DEF Traffic Lights Defective  
SIGNS Road Signs Defective or Obscured  
RD WRKS Road Works  
Surface Road Surface Defective



# D-PRINT CRASH REPORT

20-Feb-2025

09:36:32

A28, Chart Rd, Ashford

Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
18	Road No A28 Section 496 Grid 599962E Ref 143144N	SLIGHT	23/11/2022	4	19:10	DRK STL	Wet/Damp	Fine			P/C
	A28, CHART RD RNDBT J/W CARLTON RD, ASHFORD.								Ashford		
	OLR: R2 was coming down Carlton rd with lights both front and rear and slowed as approached the rndbt, went across towards Sir Henry Brackenberry Rd. As went around the rndbt, V1 approached the rndbt from along Chart rd from the Great Chart direction. V1 was in the right-hand lane as they approached the rndbt was coming at a high speed. V1 did not slow down but maintained speed and hit the back of bicycle. V1 did not slow down but carried on driving and went up Templer way. V1 did not stop but hit V2. As R2 was hit, bike swung around as V1 hit the back of bike and R2 came off.						Veh1, car, SW -> N Veh2, pedal cycle, SE -> NW			Casualties 1 Vehicles 2	
19	Road No A28 Section 496 Grid 599966E Ref 143127N	SLIGHT	20/01/2023	6	10:24	L	Dry	Fine			HGV M/C
	A28, CHART RD RNDBT J/W CHART RD, ASHFORD.								Ashford		
	OLR: R2 was in the left lane going around the roundabout on the Great Chart Rd. Roundabout was clear as R2 was exiting the roundabout to continue to go forward, V1/lorry came across and knocked R2 off motorbike. V1 sped off quickly.						Veh1, goods > 7.5t, E -> W Veh2, m/cycle 50 - 125cc, N -> SW			Casualties 1 Vehicles 2	

## Key Involved

PED Pedestrian  
HGV Heavy Goods Vehicle  
GV Goods Vehicle  
M/C Motor Cycle  
P/C Pedal Cycle  
PSV Bus/Coach

## Street Lighting

L Daylight  
STL Street Lights  
USL Street Lights Unlit  
NSL No Street Lights  
STU Street Lights Unknown

## FACTORS

+VE Positive Breath Test  
R.TURN Right Turn Manoeuvre  
O/TAKE Overtaking Manoeuvre  
S.VEH Single Vehicle

## Special Conditions

ATS OUT Traffic Lights Not Working  
ATS DEF Traffic Lights Defective  
SIGNS Road Signs Defective or Obscured  
RD WRKS Road Works  
Surface Road Surface Defective

# D-PRINT CRASH REPORT

20-Feb-2025

09:36:32

A28, Chart Rd, Ashford

Accident Date BETWEEN '01-Oct-2021' AND '30-Sep-2024'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
20	Road No A28 Section 163 Grid 599976E Ref 143127N	SLIGHT	29/11/2023	4	13:00	L	Dry	Fine			P/C
	A28 CHART ROAD ROUNDABOUT NEAR J/W CARLTON ROAD, ASHFORD								Ashford		
	Taken from Online Report: V2 pedal cycle was on the roundabout signalling right to go towards Sir Henry Brackenbury Road. They put their hands back on the handlebars and V1 cut across them and drove into them hard. The impact must have damaged their vehicle. As it passed V2 they fell to the ground on their right side. V1 drove off and failed to stop. (exact position on rndbt not confirmed)						Veh1, car, S -> N Veh2, pedal cycle, E -> W			Casualties 1 Vehicles 2	

## Key Involved

PED Pedestrian  
HGV Heavy Goods Vehicle  
GV Goods Vehicle  
M/C Motor Cycle  
P/C Pedal Cycle  
PSV Bus/Coach

## Street Lighting

L Daylight  
STL Street Lights  
USL Street Lights Unlit  
NSL No Street Lights  
STU Street Lights Unknown

## FACTORS

+VE Positive Breath Test  
R.TURN Right Turn Manoeuvre  
O/TAKE Overtaking Manoeuvre  
S.VEH Single Vehicle

## Special Conditions

ATS OUT Traffic Lights Not Working  
ATS DEF Traffic Lights Defective  
SIGNS Road Signs Defective or Obscured  
RD WRKS Road Works  
Surface Road Surface Defective